

# ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE REGULATORY CONTACT RECORD

---

**Date/Time:** April 19, 2004 / 11:00 am

**Site Contact(s):** Sarah Roberts  
**Phone:** 303-966-3008

**Regulatory Contact:** Denise Onyskiw  
**Phone:** 303-692-3371  
**Agency:** CDPHE

---

**Purpose of Contact:** Radiological Surveys for Building 715

---

## Discussion

Building 715, the structure that housed the diesel emergency generator #1 for Building 771, has been vacated and are destined for demolition or removal. The *Reconnaissance Level Characterization Report (RLCR) Supplement, 771 Annex, Stack and Outbuildings, Building 771 Closure Project, Revision 2* was approved on July 12, 2001. Building 715 was included in the RLCR as a Type 1 facility. Given that the facility remained in use following the radiological surveys provided in the RLCR, CDPHE's concurrence letter requires additional radiological survey data be provided, as necessary, prior to closure/demolition. As a result, additional radiological survey data was provided to Ms. Onyskiw on April 19, 2004. CDPHE concurred that the additional radiological data provided is sufficient to supplement the previous data and function as the pre-demolition survey.

---

**Contact Record Prepared By:** Sarah Roberts

---

## Required Distribution:

P. Arnold, K-H 371	J. Legare, DOE
C. Deck, K-H	R. Leitner, K-H 371
R. DiSalvo	J. Mead, K-H ESS
C. Gilbreath, K-H 771	S. Nesta, K-H RISS
S. Gunderson, CDPHE	K. North, K-H ESS/MS
L. Kilpatrick, RFFO	T. Rehder, USEPA
	D. Shelton, K-H

## Additional Distribution:

D. Onyskiw, CDPHE  
D. Kruchek, CDPHE  
W. Seyfert, DOE

